٠ بندان	Approved For Release 2002/06/13 ICIA RDPX B00878R000600010	135-100 TING
ाक्षाद्धः	1850Z 23 MAR 60 SECRET 3 53	3 6
from :	DIRECTOR 25X1A DPD (1,2,3,4,5,6,7,8,9,10) 5 (5 (11))	ROUTINE
a OTAL	S/C (11) VP 25X1A TOR: 1935Z 23 MAR 6Ø 3	25X1A IN 21179
10		az4851
25X1A	REF ECP 21-1 RECOMMEND APPROVAL. THIS PRECAUTION HAS BEEN TAK TECHNICIANS FOR SEVERAL YEARS. THE PRIMARY REASON F	
•	DELEASE CARLE ACCEMBLY ANTH PINE COTT CORRED MIRE 10	THAT THE

RECOMMEND APPROVAL. THIS PRECAUTION HAS BEEN TAKEN BY FIRWEL

TECHNICIANS FOR SEVERAL YEARS. THE PRIMARY REASON FOR SECURING

RELEASE CABLE ASSEMBLY WITH FINE SOFT COPPER WIRE IS THAT THE

AIRCRAFT OXYGEN SUPPLY INLET PRESSURE TO SEAT PACK CAUSES THE

EMERGENCY OXYGEN RELEASE PIN TO FIT LOOSELY IN ITS BRACKET AND

ALTHOUGH A FINE SOFT COPPER WIRE WILL NOT HINDER NORMAL OPERATION

OF THE EMERGENCY SUPPLY SYSTEM THE RELEASE PIN WILL BE RESTRAINED

FROM VIBRATING OUT OF THE OFF POSITION. PRESENTLY 25X1A

USES NUMBER 28 SOFT COPPER LOCKWIRE FOR THIS PURPOSE.

END OF MESSAGE